

## Device Errata

MPC850CE/D  
Rev. 3, 2/2003

MPC850 Device Errata  
Reference



**MOTOROLA**  
intelligence everywhere™

*digitaldna*™

The MPC850 User's Manual has two User's Manual errata which are explained below. These errata will be in the next revision of the User's Manual Errata that goes out and deleted from the text below.

This document is a compilation of all MPC850 Family device errata from Revision 0.0 forward. Herein, the errata are classified and numbered, and each erratum is provided with a description and workarounds.

To find which errata apply to your particular device, please refer to the errata listings for each revision provided in the following pages.

### **PLL Loss of Lock**

It should be noted that the PLL loss of lock detection as described in the MPC850 PowerQUICC Users Manual Rev 1. Section 11.1.3.1 and similar sections for all MPC8XX family devices does not have a specification for the detection threshold to determine loss of lock. Therefore the user should use this feature as a debug tool only for all MPC8XX family devices and not in their production systems. Characterization of the threshold value over temperature and operating voltages has shown that the threshold can be triggered when clock out to clock in phase differences is 1.8 ns. or greater.

### **XFC Capacitor Recommendations**

The current MPC850 PowerQUICC Users Manual Section 14.2.2.3 Table 14-2 ("XFC Capacitor Values Based on the MF Field" ) shows the recommended XFC values which should be replaced with the table shown below.

**Table 1. XFC Capacitor Values Based on the MF Field**

MF Range	Minimum Capacitance	Maximum Capacitance	Unit
$1 \leq (MF+1) \leq 4$	$XFC = [(MF + 1) \times 425] - 125$	$XFC = [(MF+1) \times 590] - 175$	pF
$(MF+1) > 4$	$XFC = (MF+1) \times 520$	$XFC = (MF+1) \times 920$	pF

## Part 1 MPC850 Revision C- Mask Set 0K44m

Version(s): MPC850, MPC850DE, MPC850DSL, MPC850SR

[Asterisks (\*) indicate errata scheduled for fix in the next revision. Carats (^) indicate errata that will not be corrected due to minimal system impact and/or availability of simple workarounds. No indication indicates errata for which fixes have not been scheduled.]

### 1.1 GLOBAL ERRATUM

^GLL1. Some registers are not initialized correctly during Power-Up RESET, HRESET\*, and SRESET\*.

### 1.2 SIU ERRATA

SIU1. Spurious External Bus Transaction Following PLPRCR Write.

SIU4. Possible External Bus Hang Occurs Under Certain Error Conditions.

^SIU10. RTC/PIT doesn't count properly.

### 1.3 CPM ERRATA

CPM14. The ERAM4K Bit in the RISC Microcode Development Support Control Register (RMDS) is Erroneously Cleared.

CPM15. USB underrun when ATM or Ethernet function is used in conjunction with USB.

### 1.4 GENERAL ERRATA

G1. Core Operation is Limited to a 3.0V Minimum.

G7. Restriction of open collector pull up.

### 1.5 CPU ERRATA

CPU1. Bus Error Unsupported by the Data Cache Burst.

CPU3. Incorrect Data Breakpoint Detection on Store Instructions.

CPU4. Program Trace Mechanism Error.

CPU6. Instruction MMU Bug at Page Boundaries in Show-all Mode.

^CPU11. Possible Excess Current Consumption in Deep Sleep Mode.

### 1.6 ATM ERRATA

ATM1. APCO Interrupts Cannot Be Masked.

\*ATM2. CPM Lockup When Issuing APC\_BYPASS When TX Queue Full.

# Part 2 MPC850 Revision B- Mask Set 4H97G / 0K24A/0K29A / 0K45m

Version(s): MPC850, MPC850DE, MPC850DSL, MPC850SR

[Asterisks (\*) indicate errata scheduled for fix in the next revision. Carats (^) indicate errata that will not be corrected due to minimal system impact and/or availability of simple workarounds. No indication indicates errata for which fixes have not been scheduled.]

## 2.1 GLOBAL ERRATUM

^GLL1. Some registers are not initialized correctly during Power-Up RESET, HRESET\*, and SRESET\*.

## 2.2 SIU ERRATA

SIU1. Spurious External Bus Transaction Following PLPRCR Write.

SIU4. Possible External Bus Hang Occurs Under Certain Error Conditions.

^SIU10. RTC/PIT doesn't count properly

## 2.3 CPM ERRATA

\*CPM5. I2C: Receiver Locks, Holding SDA Low.

CPM14. The ERAM4K Bit in the RISC Microcode Development Support Control Register (RMDS) is Erroneously Cleared.

CPM15. USB underrun when ATM or Ethernet function is used in conjunction with USB.

\*CPM16. USB endpoint lock up.

\*CPM 17. USB occasionally ignores tokens, violates USB protocol by providing incorrect responses, etc.

## 2.4 GENERAL ERRATA

G1. Core Operation is Limited to a 3.0V Minimum.

G7. Restriction of open collector pull up.

## 2.5 CPU ERRATA

CPU1. Bus Error Unsupported by the Data Cache Burst.

CPU3. Incorrect Data Breakpoint Detection on Store Instructions.

CPU4. Program Trace Mechanism Error.

CPU6. Instruction MMU Bug at Page Boundaries in Show-all Mode.

^CPU11. Possible Excess Current Consumption in Deep Sleep Mode.

## 2.6 ATM ERRATA

ATM1. APCO Interrupts Cannot Be Masked.

\*ATM2. CPM Lockup When Issuing APC\_BYPASS When TX Queue Full.

# Part 3 MPC850 Revision A - Mask Set 0H89G, 2H89G

Version(s): MPC850, MPC850DC, MPC850DE, MPC850DH, MPC850SAR

[Asterisks (\*) indicate errata scheduled for fix in the next revision. Carats (^) indicate errata that will not be corrected due to minimal system impact and/or availability of simple workarounds. No indication indicates errata for which fixes have not been scheduled.]

## 3.1 GLOBAL ERRATUM

^GLL1. Some registers are not initialized correctly during Power-Up RESET, HRESET\*, and SRESET\*.

## 3.2 SIU ERRATA

SIU1. Spurious External Bus Transaction Following PLPRCR Write.

\*SIU2. Missed DRAM Refresh Cycles with External Masters.

SIU4. Possible External Bus Hang Occurs Under Certain Error Conditions.

^SIU10. RTC/PIT doesn't count properly

## 3.3 CPM ERRATA

\*CPM1. I2C: Receive Problem in Arbitration-Lost State.

\*CPM3. I2C: Master Fails to Receive After Executing Read or Write.

\*CPM4. I2C: Receives Single-Byte Buffers After Failed Transaction.

CPM5. I2C: Receiver Locks, Holding SDA Low.

\*CPM6. I2C: Master Collision After 'Double Start'.

\*CPM7. I2C: Short Aborted Transmission After NACK.

\*CPM8. I2C: Split Receiver Buffer Between Loopback and Read.

\*CPM9. I2C: Spurious BUSY Errors After Reception in I2C Master Mode.

\*CPM11. I2C: Port A Pin (PA13) May Consume Excess Current in Deep-Sleep Mode.

\*CPM12. I2C: Improper USB Initialization May Cause Excess Current in Deep-Sleep Mode.

\*CPM13. I2C: Port B Pin PB25 Fails to Function as TXD3.

CPM14. The ERAM4K Bit in the RISC Microcode Development Support Control Register (RMDS) is Erroneously Cleared.

CPM15. USB underrun when ATM or Ethernet function is used in conjunction with USB.

\*CPM16. USB endpoint lock up.

\*CPM 17. USB occasionally ignores tokens, violates USB protocol by providing incorrect responses, etc.

## 3.4 GENERAL ERRATA

G1. Core Operation is Limited to a 3.0V Minimum.

\*G3. EXTCLK and CLKOUT Clocks May Not Be in Phase in Half-Speed Bus Mode.

\*G4. Potential Problems Caused by Skew Between EXTCLK and CLKOUT.

G7. Restriction of open collector pull up.

## 3.5 CPU ERRATA

CPU1. Bus Error Unsupported by the Data Cache Burst.

CPU3. Incorrect Data Breakpoint Detection on Store Instructions.

CPU4. Program Trace Mechanism Error.

CPU6. Instruction MMU Bug at Page Boundaries in Show-all Mode.

\*CPU8. Branch Prediction with Sequential Branch Instructions.

\*CPU9. Missed Instruction After Conditional Branch

\*CPU10. Instruction Sequencer Error When Modifying MSR with Interrupts Enabled.

^CPU11. Possible Excess Current Consumption in Deep Sleep Mode.

## 3.6 ATM ERRATA

ATM1. APCO Interrupts Cannot Be Masked.

ATM2. CPM Lockup When Issuing APC\_BYPASS When TX Queue Full.

\*ATM3. Incorrect Operation in Presync State of Cell Delineation.

## Part 4 MPC850 Revision 0.3- Mask Set 3F98S

Version(s): MPC850, MPC850SE

[Asterisks (\*) indicate errata scheduled for fix in the next revision. Carats (^) indicate errata that will not be corrected due to minimal system impact and/or availability of simple workarounds. No indication indicates errata for which fixes have not been scheduled.]

### 4.1 GLOBAL ERRATUM

^GLL1. Some registers are not initialized correctly during Power-Up RESET, HRESET\*, and SRESET\*.

### 4.2 SIU ERRATA

SIU1. Spurious External Bus Transaction Following PLPRCR Write.

SIU2. Missed DRAM Refresh Cycles with External Masters.

\*SIU3. Lock/Unlock Function of RSR Also Locks/Unlocks SCCR.

SIU4. Possible External Bus Hang Occurs Under Certain Error Conditions.

^SIU10. RTC/PIT doesn't count properly.

### 4.3 CPM ERRATA

CPM1. I2C: Receive Problem in Arbitration-Lost State.

\*CPM2. I2C: Error in FLT Bit.

CPM3. I2C: Master Fails to Receive After Executing Read or Write.

CPM4. I2C: Receives Single-Byte Buffers After Failed Transaction.

CPM5. I2C: Receiver Locks, Holding SDA Low.

CPM6. I2C: Master Collision After 'Double Start'.

CPM7. I2C: Short Aborted Transmission After NACK.

CPM8. I2C: Split Receiver Buffer Between Loopback and Read.

CPM9. I2C: Spurious BUSY Errors After Reception in I2C Master Mode.

CPM11. I2C: Port A Pin (PA13) May Consume Excess Current in Deep-Sleep Mode.

CPM12. I2C: Improper USB Initialization May Cause Excess Current in Deep-Sleep Mode.

CPM14. The ERAM4K Bit in the RISC Microcode Development Support Control Register (RMDS) is Erroneously Cleared.

CPM15. USB underrun when ATM or Ethernet function is used in conjunction with USB.

\*CPM16. USB endpoint lock up.

\*CPM 17. USB occasionally ignores tokens, violates USB protocol by providing incorrect responses, etc.

## 4.4 GENERAL ERRATA

G1. Core Operation is Limited to a 3.0V Minimum.

G3. EXTCLK and CLKOUT Clocks May Not Be in Phase in Half-Speed Bus Mode.

G4. Potential Problems Caused by Skew Between EXTCLK and CLKOUT.

\*G5. ESD Breakdown Voltage for XFC Pin Less Than Motorola-Imposed Requirements.

\*G6. Active Pullup Drivers Switch to High-Impedance Too Early.

G7. Restriction of open collector pull up.

## 4.5 CPU ERRATA

CPU1. Bus Error Unsupported by the Data Cache Burst.

\*CPU2. D-Cache Presents Valid Data When Parity Error Present on a Burst.

CPU3. Incorrect Data Breakpoint Detection on Store Instructions.

CPU4. Program Trace Mechanism Error.

CPU6. Instruction MMU Bug at Page Boundaries in Show-all Mode.

CPU7. Possible Data Cache Corruption When Writing SPRs.

CPU8. Branch Prediction with Sequential Branch Instructions.

CPU9. Missed Instruction After Conditional Branch

CPU10. Instruction Sequencer Error When Modifying MSR with Interrupts Enabled.

^CPU11. Possible Excess Current Consumption in Deep Sleep Mode.

## 4.6 VIDEO CONTROLLER ERRATUM

VC1. Video Output Gets Stuck In Background Mode.



# Part 5 MPC850 Revision 0.2- Mask Set 2F98S

Version(s): MPC850, MPC850SE

[Asterisks (\*) indicate errata scheduled for fix in the next revision. Carats (^) indicate errata that will not be corrected due to minimal system impact and/or availability of simple workarounds. No indication indicates errata for which fixes have not been scheduled.]

## 5.1 GLOBAL ERRATUM

^GLL1. Some registers are not initialized correctly during Power-Up RESET, HRESET\*, and SRESET\*.

## 5.2 SIU ERRATA

SIU1. Spurious External Bus Transaction Following PLPRCR Write.

SIU2. Missed DRAM Refresh Cycles with External Masters.

SIU3. Lock/Unlock Function of RSR Also Locks/Unlocks SCCR.

SIU4. Possible External Bus Hang Occurs Under Certain Error Conditions.

^SIU10. RTC/PIT doesn't count properly.

## 5.3 CPM ERRATA

CPM1. I2C: Receive Problem in Arbitration-Lost State.

CPM2. I2C: Error in FLT Bit.

CPM3. I2C: Master Fails to Receive After Executing Read or Write.

CPM4. I2C: Receives Single-Byte Buffers After Failed Transaction.

CPM5. I2C: Receiver Locks, Holding SDA Low.

CPM6. I2C: Master Collision After 'Double Start'.

CPM7. I2C: Short Aborted Transmission After NACK.

CPM8. I2C: Split Receiver Buffer Between Loopback and Read.

CPM9. I2C: Spurious BUSY Errors After Reception in I2C Master Mode.

\*CPM10. I2C: USB Microcode May Duplicate First Byte For IN Token Transfer.

CPM11. I2C: Port A Pin (PA13) May Consume Excess Current in Deep-Sleep Mode.

CPM12. I2C: Improper USB Initialization May Cause Excess Current in Deep-Sleep Mode.

CPM14. The ERAM4K Bit in the RISC Microcode Development Support Control Register (RMDS) is Erroneously Cleared.

CPM15. USB underrun when ATM or Ethernet function is used in conjunction with USB.

\*CPM16. USB endpoint lock up.

\*CPM 17. USB occasionally ignores tokens, violates USB protocol by providing incorrect responses, etc.

## 5.4 GENERAL ERRATA

- G1. Core Operation is Limited to a 3.0V Minimum.
- G3. EXTCLK and CLKOUT Clocks May Not Be in Phase in Half-Speed Bus Mode.
- G4. Potential Problems Caused by Skew Between EXTCLK and CLKOUT.
- G5. ESD Breakdown Voltage for XFC Pin Less Than Motorola-Imposed Requirements.
- G6. Active Pullup Drivers Switch to High-Impedance Too Early.
- G7. Restriction of open collector pull up.

## 5.5 CPU ERRATA

- CPU1. Bus Error Unsupported by the Data Cache Burst.
- CPU2. D-Cache Presents Valid Data When Parity Error Present on a Burst.
- CPU3. Incorrect Data Breakpoint Detection on Store Instructions.
- CPU4. Program Trace Mechanism Error.
- CPU6. Instruction MMU Bug at Page Boundaries in Show-all Mode.
- CPU7. Possible Data Cache Corruption When Writing SPRs.
- CPU8. Branch Prediction with Sequential Branch Instructions.
- CPU9. Missed Instruction After Conditional Branch
- CPU10. Instruction Sequencer Error When Modifying MSR with Interrupts Enabled.
- ^CPU11. Possible Excess Current Consumption in Deep Sleep Mode.

# Part 6 MPC850 Revision 0.1- Mask Set 1F98S

Version(s): MPC850, MPC850SE

[Asterisks (\*) indicate errata scheduled for fix in the next revision. Carats (^) indicate errata that will not be corrected due to minimal system impact and/or availability of simple workarounds. No indication indicates errata for which fixes have not been scheduled.]

## 6.1 GLOBAL ERRATUM

^GLL1. Some registers are not initialized correctly during Power-Up RESET, HRESET\*, and SRESET\*.

## 6.2 SIU ERRATA

SIU1. Spurious External Bus Transaction Following PLPRCR Write.

SIU2. Missed DRAM Refresh Cycles with External Masters.

SIU3. Lock/Unlock Function of RSR Also Locks/Unlocks SCCR.

SIU4. Possible External Bus Hang Occurs Under Certain Error Conditions.

^SIU10. RTC/PIT doesn't count properly.

## 6.3 CPM ERRATA

CPM1. I2C: Receive Problem in Arbitration-Lost State.

CPM2. I2C: Error in FLT Bit.

CPM3. I2C: Master Fails to Receive After Executing Write.

CPM4. I2C: Receives Single-Byte Buffers After Failed Transaction.

CPM5. I2C: Receiver Locks, Holding SDA Low.

CPM6. I2C: Master Collision After 'Double Start'.

CPM7. I2C: Short Aborted Transmission After NACK.

CPM8. I2C: Split Receiver Buffer Between Loopback and Read.

CPM9. I2C: Spurious BUSY Errors After Reception in I2C Master Mode.

CPM10. I2C: USB Microcode May Duplicate First Byte For IN Token Transfer.

CPM11. I2C: Port A Pin (PA13) May Consume Excess Current in Deep-Sleep Mode.

CPM12. I2C: Improper USB Initialization May Cause Excess Current in Deep-Sleep Mode.

CPM14. The ERAM4K Bit in the RISC Microcode Development Support Control Register (RMDS) is Erroneously Cleared.

CPM15. USB underrun when ATM or Ethernet function is used in conjunction with USB.

\*CPM16. USB endpoint lock up.

\*CPM 17. USB occasionally ignores tokens, violates USB protocol by providing incorrect responses, etc.

## 6.4 GENERAL ERRATA

G1. Core Operation is Limited to a 3.0V Minimum.

\*G2. Higher Than Expected Keep Alive Power (KAPWR) Current When Main Power (VDDH & VDDL) is Removed.

G3. EXTCLK and CLKOUT Clocks May Not Be in Phase in Half-Speed Bus Mode.

G4. Potential Problems Caused by Skew Between EXTCLK and CLKOUT.

G5. ESD Breakdown Voltage for XFC Pin Less Than Motorola-Imposed Requirements.

G6. Active Pullup Drivers Switch to High-Impedance Too Early.

G7. Restriction of open collector pull up.

## 6.5 CPU ERRATA

CPU1. Bus Error Unsupported by the Data Cache Burst.

CPU2. D-Cache Presents Valid Data When Parity Error Present on a Burst.

CPU3. Incorrect Data Breakpoint Detection on Store Instructions.

CPU4. Program Trace Mechanism Error.

CPU6. Instruction MMU Bug at Page Boundaries in Show-all Mode.

CPU7. Possible Data Cache Corruption When Writing SPRs.

CPU8. Branch Prediction with Sequential Branch Instructions.

CPU9. Missed Instruction After Conditional Branch

CPU10. Instruction Sequencer Error When Modifying MSR with Interrupts Enabled.

^CPU11. Possible Excess Current Consumption in Deep Sleep Mode.

# Part 7 MPC850 Revision 0.0- Mask Set 0F98S

Version(s): MPC850, MPC850SE

[Asterisks (\*) indicate errata scheduled for fix in the next revision. Carats (^) indicate errata that will not be corrected due to minimal system impact and/or availability of simple workarounds. No indication indicates errata for which fixes have not been scheduled.]

## 7.1 GLOBAL ERRATUM

^GLL1. Some registers are not initialized correctly during Power-Up RESET, HRESET\*, and SRESET\*.

## 7.2 SIU ERRATA

SIU1. Spurious External Bus Transaction Following PLPRCR Write.

SIU2. Missed DRAM Refresh Cycles with External Masters.

SIU3. Lock/Unlock Function of RSR Also Locks/Unlocks SCCR.

SIU4. Possible External Bus Hang Occurs Under Certain Error Conditions.

^SIU10. RTC/PIT doesn't count properly.

## 7.3 CPM ERRATA

CPM1. I2C: Receive Problem in Arbitration-Lost State.

CPM2. I2C: Error in FLT Bit.

CPM3. I2C: Master Fails to Receive After Executing Read or Write.

CPM4. I2C: Receives Single-Byte Buffers After Failed Transaction.

CPM5. I2C: Receiver Locks, Holding SDA Low.

CPM6. I2C: Master Collision After 'Double Start'.

CPM7. I2C: Short Aborted Transmission After NACK.

CPM8. I2C: Split Receiver Buffer Between Loopback and Read.

CPM9. I2C: Spurious BUSY Errors After Reception in I2C Master Mode.

CPM10. I2C: USB Microcode May Duplicate First Byte For IN Token Transfer.

CPM11. I2C: Port A Pin (PA13) May Consume Excess Current in Deep-Sleep Mode.

CPM12. I2C: Improper USB Initialization May Cause Excess Current in Deep-Sleep Mode.

CPM14. The ERAM4K Bit in the RISC Microcode Development Support Control Register (RMDS) is Erroneously Cleared.

CPM15. USB underrun when ATM or Ethernet function is used in conjunction with USB.

\*CPM16. USB endpoint lock up.

\*CPM 17. USB occasionally ignores tokens, violates USB protocol by providing incorrect responses, etc.

## 7.4 GENERAL ERRATA

G1. Core Operation is Limited to a 3.0V Minimum.

G2. Higher Than Expected Keep Alive Power (KAPWR) Current When Main Power (VDDH & VDDL) is Removed.

G3. EXTCLK and CLKOUT Clocks May Not Be in Phase in Half-Speed Bus Mode.

G4. Potential Problems Caused by Skew Between EXTCLK and CLKOUT.

G5. ESD Breakdown Voltage for XFC Pin Less Than Motorola-Imposed Requirements.

G6. Active Pullup Drivers Switch to High-Impedance Too Early.

G7. Restriction of open collector pull up.

## 7.5 CPU ERRATA

CPU1. Bus Error Unsupported by the Data Cache Burst.

CPU2. D-Cache Presents Valid Data When Parity Error Present on a Burst.

CPU3. Incorrect Data Breakpoint Detection on Store Instructions.

CPU4. Program Trace Mechanism Error.

\*CPU5. Instruction Cache Replacement Policy Bug.

CPU6. Instruction MMU Bug at Page Boundaries in Show-all Mode.

CPU7. Possible Data Cache Corruption When Writing SPRs.

CPU8. Branch Prediction with Sequential Branch Instructions.

CPU9. Missed Instruction After Conditional Branch

CPU10. Instruction Sequencer Error When Modifying MSR with Interrupts Enabled.

^CPU11. Possible Excess Current Consumption in Deep Sleep Mode.

## Part 8 ERRATA LIST

### 8.1 Global ErratUM

#### GLL1. Some registers are not initialized correctly during Power-Up RESET, HRESET\*, and SRESET\*.

The following table is provided to clarify/correct the power-on RESET value of many of the registers and lists whether each register is affected by HRESET\* and/or SRESET\*. The table applies for the MPC850 Family, the MPC855T, the MPC857T, the MPC860 Family, and the MPC862 Family.

**Table 1. Power-On Reset of Registers**

REGISTER	Value at Power-On RESET*	Affected by HRESET*	Affected by SRESET*
SIUMCR	01200000	YES	NO
SYPCR	FFFFFF07	YES	NO
SWSR	0	YES	YES
SIPEND	0000xxxx	YES	YES
SIMASK	0000xxxx	YES	YES
SIEL	0000xxxx	YES	NO
SIVEC	(xx11)(11xx)xxxxxx	YES	YES
TESR	XXXX0000	YES	YES
SDCR	0	YES	NO
PBR0	x	NO	NO
POR0	x	NO	NO
PBR1	x	NO	NO
POR1	x	NO	NO
PBR2	x	NO	NO
POR2	x	NO	NO
PBR3	x	NO	NO
POR3	x	NO	NO
PBR4	x	NO	NO
POR4	x	NO	NO
PBR5	x	NO	NO
POR5	x	NO	NO
PBR6	x	NO	NO
POR6	x	NO	NO
PBR7	x	NO	NO
POR7	x	NO	NO
PGCRA	0	YES	NO
PGCRB	0	YES	NO
PSCR	x	NO	NO
PIPR	??00??00	YES	YES
PER	0	YES	YES
BR0	XXXXX(??00)0(000?)	YES	NO
OR0	0000FF4	YES	NO
BR1	XXXXXX(xx00)0	YES	NO
OR1	XXXXXXXX(xx0)	YES	NO

Table 1. Power-On Reset of Registers

REGISTER	Value at Power-On RESET*	Affected by HRESET*	Affected by SRESET*
BR2	XXXXXX(xx00)0	YES	NO
OR2	XXXXXX(xx00)0	YES	NO
BR3	XXXXXX(xx00)0	YES	NO
OR3	XXXXXX(xx00)0	YES	NO
BR4	XXXXXX(xx00)0	YES	NO
OR4	XXXXXX(xx00)0	YES	NO
BR5	XXXXXX(xx00)0	YES	NO
OR5	XXXXXX(xx00)0	YES	NO
BR6	XXXXXX(xx00)0	YES	NO
OR6	XXXXXX(xx00)0	YES	NO
BR7	XXXXXX(xx00)0	YES	NO
OR7	XXXXXX(xx00)0	YES	NO
MAR	x	NO	NO
MCR	(xx00)0(x000)0(0xx0)X(00xx)X	YES	NO
MAMR	xx001000	YES	NO
MBMR	xx001000	YES	NO
MSTAT	0	YES	NO
MPTPR	0200	YES	NO
MDR	x	NO	NO
TBSCR	0	YES	NO
TBREFA	x	NO	NO
TBREFB	x	NO	NO
RTCSC	00(000x)(000x)	YES	YES
RTC	x	NO	YES
RTSEC	x	NO	YES
RTCAL	x	NO	NO
PISCR	0	YES	NO
PITC	x	NO	NO
PITR	x	N/A	N/A
SCCR	0(000?)(?000)(0??0)0000	YES	NO
PLPRCR	???0(0100)000	YES	YES
RSR	0	YES	YES
TBSCRK	x	YES	YES
TBREFAK	x	YES	YES
TBREFBK	x	YES	YES
TBK	x	YES	YES
RTCSCK	x	YES	YES
RTCK	x	YES	YES
RTSECK	x	YES	YES
RTCALK	x	YES	YES
PISCRK	x	YES	YES
PITCK	x	YES	YES
SCCRK	x	YES	YES
PLPRCK	x	YES	YES
RSRK	x	YES	YES
I2MOD	0	YES	YES



**Table 1. Power-On Reset of Registers**

REGISTER	Value at Power-On RESET*	Affected by HRESET*	Affected by SRESET*
I2ADD	x	NO	NO
I2BRG	FFFF	YES	NO
I2COM	0	YES	YES
I2CER	0	YES	YES
I2CMR	0	YES	YES
SDAR	x	NO	NO
SDSR	0	YES	YES
SDMR	0	YES	YES
IDSR1	0	YES	YES
IDMR1	0	YES	YES
IDSR2	0	YES	YES
IDMR2	0	YES	YES
CIVR	0	YES	YES
CICR	0	YES	NO
CIPR	0	YES	YES
CIMR	0	YES	YES
CISR	0	YES	YES
PADIR	0	YES	NO
PAPAR	0	YES	NO
PAODR	0	YES	NO
PADAT	x	NO	NO
PCDIR	0	YES	NO
PCPAR	0	YES	NO
PCSO	0	YES	NO
PCDAT	x	NO	NO
PCINT	0	YES	NO
PDDIR	0	YES	NO
PDPAR	0	YES	NO
PDDAT	x	NO	NO
TGCR	0	YES	YES
TMR1	0	YES	YES
TMR2	0	YES	YES
TRR1	FFFF	YES	YES
TRR2	FFFF	YES	YES
TCR1	0	YES	YES
TCR2	0	YES	YES
TCN1	0	YES	YES
TCN2	0	YES	YES
TMR3	0	YES	YES
TMR4	0	YES	YES
TRR3	FFFF	YES	YES
TRR4	FFFF	YES	YES
TCR3	0	YES	YES
TCR4	0	YES	YES
TCN3	0	YES	YES
TCN4	0	YES	YES

**Table 1. Power-On Reset of Registers**

REGISTER	Value at Power-On RESET*	Affected by HRESET*	Affected by SRESET*
TER1	0	YES	YES
TER2	0	YES	YES
TER3	0	YES	YES
TER4	0	YES	YES
CPCR	0	YES	YES
RCCR	0	YES	NO
RCTR1	NA	YES	YES
RCTR2	NA	YES	YES
RCTR3	NA	YES	YES
RCTR4	NA	YES	YES
RTER	0	YES	YES
RTMR	0	YES	YES
BRGC1	0	YES	NO
BRGC2	0	YES	NO
BRGC3	0	YES	NO
BRGC4	0	YES	NO
GSMR_L1	0	YES	YES
GSMR_H1	0	YES	YES
PSMR1	0	YES	YES
TODR1	0	YES	YES
DSR1	7E7E	YES	YES
SCCE1	0	YES	YES
SCCM1	0	YES	YES
SCCS1	0	YES	YES
GSMR_L2	0	YES	YES
GSMR_H2	0	YES	YES
PSMR2	0	YES	YES
TODR2	0	YES	YES
DSR2	7E7E	YES	YES
SCCE2	0	YES	YES
SCCM2	0	YES	YES
SCCS2	0	YES	YES
GSMR_L3	0	YES	YES
GSMR_H3	0	YES	YES
PSMR3	0	YES	YES
TODR3	0	YES	YES
DSR3	7E7E	YES	YES
SCCE3	0	YES	YES
SCCM3	0	YES	YES
SCCS3	0	YES	YES
GSMR_L4	0	YES	YES
GSMR_H4	0	YES	YES
PSMR4	0	YES	YES
TODR4	0	YES	YES
DSR4	7E7E	YES	YES
SCCE4	0	YES	YES

**Table 1. Power-On Reset of Registers**

REGISTER	Value at Power-On RESET*	Affected by HRESET*	Affected by SRESET*
SCCM4	0	YES	YES
SCCS4	0	YES	YES
SMCMR1	0	YES	YES
SMCE1	0	YES	YES
SMCM1	0	YES	YES
SMCMR2	0	YES	YES
SMCE2	0	YES	YES
SMCM2	0	YES	YES
SPMODE	0	YES	YES
SPIE	0	YES	YES
SPIM	0	YES	YES
SPCOM	0	YES	YES
PIPC	0	YES	NO
PTPR	0	YES	NO
PBDIR	xxx(xx00)0000	YES	NO
PBPAR	xxx(xx00)0000	YES	NO
PBODR	0	YES	NO
PBDAT	x	YES	YES
SIMODE	0	YES	YES
SIGMR	0	YES	NO
SISTR	0	YES	NO
SICMR	0	YES	YES
SICR	0	YES	NO
SIRP	0	YES	YES

**Legend:**

x or X = "don't care" in either bits, nibbles, or the entire register.

0 = a single zero indicates the entire register is reset to zeros.

( ) = isolates bits of a nibble of the register.

? = a don't care for POR, but if this register is affected by HRESET\* or SRESET\*, indicates that the value will remain the same as what it was before the reset occurred.

NA = Not Applicable, indicates that this register has no POR value.

## 8.2 SIU Errata

### SIU1. Spurious External Bus Transaction Following PLPRCR Write.

This erratum only affects some designs which execute code from synchronous memories or bus slaves.

Spurious external bus transactions can occur after executing a store to the PLPRCR register which changes the PLL multiplication factor (MF bits). This store causes the PLL to freeze the clocks while another external bus access is already visible on the pins of the chip. This appears externally as a transaction which begins, has its clocks frozen, and then is abruptly aborted without following the bus protocol.

This behavior will only affect systems with bus slaves that implement synchronous state machines that are sensitive to bus protocol violations. Synchronous DRAMs are not affected, and synchronous bus slaves that ignore bus signals when not selected (e.g. Tundra QSPAN) are not affected.

## SIU Errata

The only cases in which this erratum will cause problems are if:

- 1) The device is executing code from a slave which implements a state machine dependent on the PowerPC bus protocol, where that state machine might ‘get lost’.
- 2) There is an external device which snoops the PowerPC bus and implements a state machine; this state machine might ‘get lost’.

The impact of this erratum has been deemed minimal, and it will therefore not be corrected.

Workaround: If the behavior described above is unacceptable in the system, the following procedure can be used to avoid the spurious external bus transaction:

The instruction which performs the store to the PLPRCR should be on a burst-aligned address with at least one isync instruction following it. The Instruction Cache should be enabled while executing this sequence. Example code performing this is as follows:

```
        bl .unlock_all
        bl .invalid_all
        bl .cache_en      # icache initialization
.
.
.
.

        lis 3, 0x0050
        ori 3, 3, 0x00C0
        b st_algn

.org main + 0x0200 ##

st_algn:    stw 3, PLPRCR_OFFSET(4) # burst aligned address
            isync                    # isync
            lis 3, 0x1234             # Any instruction
            lis 3, 0x1234             # Any instruction
```

## SIU2. Missed DRAM Refresh Cycles with External Masters.

IF the MPC850 is using internal arbitration (SIUMCR[EARB]=0) AND the arbitration request level (SIUMCR[EARP]) for external masters is greater than zero,

THEN if a request by an external master (signalled by  $\overline{\text{DREQ}}$ ) occurs simultaneously with a request from the DRAM refresh controller, then the request from the DRAM refresh controller will be cancelled. This will result in a missed refresh cycle. In a system with many bus requests by external masters, this can potentially result in the cancellation of all DRAM refreshes.

Workarounds:

1) Program SIUMCR[EARP] to zero.

2) Increase the refresh rate to compensate for the potential cancellation of refresh cycles. Treated probabilistically, it should be possible to keep the refresh rate above a minimum intended rate. This is difficult to model exactly, but can be roughly estimated. For the following discussion:

$N$  = proportion of bus bandwidth used by internal MPC850 masters (other than refresh)

$E$  = proportion of bus bandwidth used by external masters

$A$  = proportion of bus bandwidth available for refresh

By definition,  $N + E + A = 1$ .

The proportion of time that a refresh request can occur is  $(E+A)$ .

The probability that a refresh request will be cancelled is  $E / (E+A)$ . If  $P$  is the probability that the refresh request will be successfully transacted, the  $P = 1 - [E / (E+A)]$ .

Therefore, to compensate for cancellation of requests, increase the refresh request rate by  $1/P$ .

For a numerical example, assume that internal and external masters each use 30% of the bus bandwidth. Thus,  $N = 0.3$ ,  $E = 0.3$ , and  $A = 0.4$ . In this example, set the refresh rate to 1.75 times the intended rate.

Note, however, that this workaround becomes impractical as  $A$  approaches zero.

3) Implement a software-controlled refresh, initiated by a periodic timer request. The user should program the PIT timer (or a CPM timer) to provide a periodic interrupt. The interrupt service routine should incorporate a software routine to refresh a memory block. This software refresh routine can consist of either reads from the appropriate DRAM page or, more simply, execution of the UPM's refresh routine via a RUN command to the MCR. The second method is recommended, as it is simpler and uses the DRAM's internal counter to keep track of the row to be refreshed. The user should choose the size of memory block to be refreshed per interrupt in order to minimize the impact of the interrupt overhead.

Let's look at an example at one extreme. Assume a system with two 4Mx32 DRAM banks controlled by CS2 and CS3. Each bank has 2048 pages (rows) and each page must be refreshed every 15.6 ms. If the UPM refresh pattern called by the software refresh routine is set up to loop 16 times (and therefore can refresh 16 rows per call), the timer interrupt should occur every  $(16/2048)*15.6\text{ms}$ , or approximately 120 $\mu\text{s}$ . If one iteration of the UPM refresh pattern is 5 clocks, the total time required to execute the software refresh routine (plus overhead for fetching instructions) for both banks is  $5*16*2+20 = 180$  clocks. Assuming an interrupt service routine entry/exit overhead of 1200 clocks, each refresh interrupt would take approximate 1400 clocks, or 28 $\mu\text{s}$  (assuming a 50MHz system clock). An ISR consuming 28 $\mu\text{s}$  out of every 120 $\mu\text{s}$  period would consume 23.3% of the CPU, with 8200 interrupts per second.

At the other extreme, we could refresh the entire memory (2048 refresh cycles per bank) every 15.6ms. In this case, the software refresh routine would require  $1200+(2048/16*180) = 24240$  clocks, or 485 $\mu\text{s}$ . In this case, the ISR would consume 485 $\mu\text{s}$  out of every 15.6ms, or 3% of the CPU, and would require only 64 interrupts per second. However, system tasks would be stalled for 485 $\mu\text{s}$  while waiting for the refresh task to complete.

The best compromise lies between. For example, at 64 pages per interrupt, the software refresh routine will consume  $1200+(64/16*18) = 1920$  clocks, or 38.5 $\mu\text{s}$ . The CPU bandwidth consumed will be  $38.5\mu\text{s}/(120\mu\text{s}*4)$  or about 8%, with about 2000 interrupts per second.

Example code implementing this software refresh follows below:

```
#=====
#This code initialize the PIT timers to interrupt (number 0) every ~24000 clocks
```

## SIU Errata

```
xor 10,0,0
ori 10,10,0xaa33
oris 10,10,0x55cc
stw 10,RTSECK_OFFSET(20) # OPEN RTC KEY

stw 10,RTSEC_OFFSET(20) # RESET RTC divider

addis 10,10,0x80
stw 10,PISCR_OFFSET(20) # CLEAR PIT INT bit

lwz 7,SCCR_OFFSET(20)
andi. 8,7,0xffff
andis. 9,7,0xff7f
or 7,8,9
oris 7,7,0x0100
stw 7,SCCR_OFFSET(20) # RTC_CLK = SYSCLK/512

xor 9,0,0
addis 9,9,0x2f
stw 9,PITC_OFFSET(20) # Int every 24000 system clocks

xor 10,0,0
addis 10,10,0x85
stw 10,PISCR_OFFSET(20) # PIT enable
sync
#=====
#The interrupt routine should include this code :
#=====
INT0 :
lhz 9,PISCR_OFFSET(20) #
sth 9,PISCR_OFFSET(20) # CLEAR PIT INT bit
andi. 9,9,0x80
bc 0x4,2,INT0_L
```

```

xor 8,8,8
ori 8,8,0x0030
oris 8,8,0x8080 # Refresh CS_0 by MCR command
stw 8,MCR_OFFSET(20) # MCR(UPMB,0x30)
stw 8,MCR_OFFSET(20) # MCR(UPMB,0x30)
stw 8,MCR_OFFSET(20) # MCR(UPMB,0x30)
stw 8,MCR_OFFSET(20) # MCR(UPMB,0x30)

```

```

ori 8,8,0x2000 # Refresh CS_1 by MCR command
stw 8,MCR_OFFSET(20) # MCR(UPMB,0x30)
stw 8,MCR_OFFSET(20) # MCR(UPMB,0x30)
stw 8,MCR_OFFSET(20) # MCR(UPMB,0x30)
stw 8,MCR_OFFSET(20) # MCR(UPMB,0x30)

```

INT0\_L: .....

^SIU10. RTC/PIT doesn't count properly.

#=====

### SIU3. Lock/Unlock Function of RSR Also Locks/Unlocks SCCR.

When the RSR is locked or unlocked via the RSRK register, the same function is also performed on the SCCR.

Workaround:

This erratum should not affect user software as long as one is aware of it. In order to avoid possible software errors due to this (if, for example, the associated code statements were reordered by the user in a code revision), as a code convention one should always perform the unlock-modify-lock operations in immediate succession on individual registers. That is: unlock the register, modify it, then lock it.

### SIU4. Possible External Bus Hang Occurs Under Certain Error Conditions

The external bus cycle may hang when the following sequence of events occur:

1. A transaction on the external bus ends as a result of an assertion of TEA or a bus monitor timeout occurs.
2. The next transaction also ends as result of an assertion of TEA or a bus monitor timeout occurs. (burt 300)

Workaround:

None. Fixed in future revision.

## SIU10. RTC/PIT doesn't count properly.

The periodic interrupt timer (PIT) consists of a 16-bit counter clocked by the PITRCLK clock supplied by the clock RTCLK(Real time clock). The 16-bit counter counts down to zero when loaded with a value from the PITC. After the timer reaches zero, the PS bit is set and an interrupt is generated if the PIE bit is a logic one. The user can program the RTC and PIT clock to be divided by 4 or 256 (depending on SCCR[RTDIV]). When the RTC clock is divided by 4, an interrupt will not occur due to a bug in the rtclk\_sync\_raw logic. The rtclk\_sync\_raw is the real time clock for the RTC timers, and its frequency is the same as rtclk\_raw. If the pll output clock is enabled and not in reset state, and the timer has not expired, then the rtclk\_sync\_raw clock has a 25% duty cycle synchronous with system T4 tick, otherwise this clock is the same as rtclk\_raw.

From the ckpspl schematics, rtclk\_raw also selects rtclk\_sync\_raw. There is no issue in the above statement when the pre-divider is set to 256 clocks, this is because the select line is slower than the selected clock source. But, when the pre-divider is set to 4, there is supposed to be a rtclk\_sync\_raw edge every 2 clocks. The rising edge of this clock will disappear due to a race between rtclk\_sync\_raw (as the select line) and the ckp\_rtclk\_sysd (as the data for the mux).

At room temperature, this will generate a spike signal, and at hot temperature, this will degrade and disappear. When this happens, the RTC will not count properly, and no interrupt will occur.

## 8.3 CPM Errata

### CPM1. I2C Receive Problem in Arbitration-Lost State.

If the MPC850 I2C master transmitter loses arbitration to another I2C master which is transmitting to the MPC850, the 860 receiver will not accept the message (address byte not acknowledged).

Workaround:

1. Avoid multimaster configuration.
2. The operation should be retried by the other master through software.

### CPM2. I2C Error in FLT bit.

An error will occur if the FLT bit is set to turn on the digital filter for the I2C. The digital filter is activated by setting the FLT bit in the I2C mode register and is turned off at reset.

(However, note that this digital filter is not required for normal operation. The MPC8xx I2C is fully compliant to the I2C specification even without this digital filter.)

Workaround:

Do not turn on the digital filter for I2C clock filter.

### CPM3. I2C Master Fails to Receive After Executing Read or Write.

If the I2C channel is in master mode, after the I2C channel performs a transaction (read or write command), the I2C channel will fail to receive a transmission from another master. It will respond with NACK.

Furthermore, after the failed reception, if the I2C master then attempts to perform another transaction (read or write command), the transaction will fail with an underrun error.

Workaround:



After the master I2C channel completes its transmission, disable and re-enable the channel in the I2MOD register (thereby resetting it).

#### **CPM4. I2C Receives Single-Byte Buffers After Failed Transaction.**

A. If the I2C channel is in master mode, then:

If the I2C master attempts a transaction (read or write command) which receives a NACK, AND the I2C master then attempts to execute a read to another slave,

THEN the master will receive the first byte of the slave's message in one buffer and will close the BD, and then will continue to receive the rest of the message in the next BDs. This reception of the first byte in a single-byte buffer will happen regardless of the MRBLR.

B. If the I2C channel is in slave mode, then:

If the I2C slave responds to a read command (i.e. performs a transmission), AND the I2C slave then responds to a write command (i.e. performs a reception),

THEN the I2C slave will receive the first byte of the master's message in one buffer and will close the BD, and then will continue to receive the rest of the message in the next BDs. This reception of the first byte in a single-byte buffer will happen regardless of the MRBLR.

Workaround:

After the I2C channel performs a transmission (master read or write, or slave response to read), disable and re-enable the channel in the I2MOD register (thereby resetting it).

#### **CPM5. I2C Receiver Locks, Holding SDA Low.**

The I2C receiver may lock up, holding the I2CSDA line low, in a system that has slow rise/fall time on the I2C clock (I2CSCL) if the environment is noisy.

Workaround:

Set the I2C predivider to 32 (by setting I2MOD[PDIV]=00), and restrict rise/fall time of I2CSCL to 0.5  $\mu$ s. In addition to this, for MPC850 revision B.0 and later, enable the digital filter via the I2MOD[FLT]. [For previous revisions of the MPC850, the digital filter is not functional.]

#### **CPM6. I2C Master Collision After 'Double Start'.**

The following situation will result in the I2C controller colliding with the transmission of another master:

- 1) Another I2C master performs a 'master write' to the I2C controller of the MPC850.
- 2) The I2C controller of the MPC850 is waiting for the I2C bus to become idle in order to become the master and perform a transaction.
- 3) The other I2C master asserts a new 'START' condition without asserting a 'STOP' condition.

In this case, the I2C master of the MPC850 will incorrectly interpret the new 'START' condition as generated by itself, and will therefore drive the I2C bus concurrently with the other master.

Workaround:

Avoid performing back-to-back START conditions on the I2C bus.

## CPM7. I2C: Short Aborted Transmission After NACK.

The following situation will cause the I2C controller of the MPC850 to send a short aborted transmission:

1) The MPC850's I2C controller performs a transaction, transmitting a buffer which has no STOP condition at the end. The next buffer (not yet transmitted) will issue a START condition, producing back-to-back transactions without an intervening STOP (also known as 'double start').

2) The MPC850's I2C controller receives a NACK on the last or next-to-last byte of the buffer.

If this case occurs, then the MPC850's I2C controller will assert a STOP condition (as expected by the I2C protocol). However, when software subsequently issues a new start command (I2COM = 0x81), the I2C master will begin its next transaction erratically. It will issue a START condition and drive one bit of the message, then drive a new START condition and restart the transmission (including the first bit).

Workaround:

Do not set up the MPC850's I2C controller to perform 'double start.'

## CPM8. I2C: Split Receive Buffer Between Loopback and Read.

IF

the MPC850's I2C master performs a loopback transaction (i.e. a master write to its own I2C address or a master write to the General Call address with General Call reception enabled).

AND

the MPC850's I2C master then performs a master read transaction

THEN

the receive buffer used for the loopback transaction will not be closed after the loopback transaction. Instead, it will be closed after the first byte of the read transaction is received. Thus, the received data from the read transaction will be split between the loopback buffer and the intended receive buffer.

Workaround:

Avoid performing loopback transactions during normal operation.

## CPM9. I2C: Spurious BUSY Errors After Reception in I2C Master Mode.

IF the MPC850's I2C controller is configured as an I2C master

AND the I2C controller is the target of another master's write,

THEN

after the MPC850 receives the data from the master (and thus closes the receive buffer appropriately), it will attempt to open the next receive buffer (even though there is no receive data). If there is no buffer available, it will generate a BUSY error.

Workaround:

Ignore BUSY errors in this case.

## CPM10. USB Microcode May Duplicate First Byte For IN Token Transfer

If an IN token for an end-point is received exactly between the time the first byte was written to the FIFO and the time the second byte is written to the FIFO, then the next IN token will be answered with a frame

that has the first byte duplicated. This is caused by the microcode aborting the in\_frame state when the IN token is received and the FIFO is not full. (burt\_XXX)

Workaround:

A microcode patch is available and will be placed on the MPC850 website. This microcode patch will ignore the fifo\_not\_ready error if FIFO filling has already started. The microcode package includes a README document, upatch (micro assembler source), upatch.map (listing), upatch.c (C-format object code), and an upatch.srx (S-record format object file).

### **CPM11. Port A Pin (PA13) May Consume Excess Current in Deep-Sleep Mode**

When the Port A pin PA13 is configured as the SCC2 function RXD2 and the IrDA logic is not enabled (i.e., the EN=0 in the IRMODE register), then the MPC850 may consume excess current due to internal contention after entering deep-sleep mode. Other than the approximate 1mA of excess current, there are no operational issues.

Workaround:

Before entering deep-sleep mode, configure PA13 as a general-purpose input. When you exit deep-sleep mode, reconfigure PA13 as the SCC2-controlled RXD2, as required.

### **CPM12. Improper USB initialization May Cause Excess Current in Deep-Sleep Mode**

An initialization problem in the USB block might cause excess current in the deep-sleep mode, typically around 500µA.

Workaround:

As part of the power-on initialization sequence, the software should enable the baud rate generator clock1 (BRGC1) by setting the EN bit to 1 and leaving it set for at least 16 system clocks before changing the serial interface clock route register from its default value (0x00000000).

### **CPM13. Port B Pin PB25 Fails to Function as TXD3**

If Port B pin PB25 is configured to function as TXD3, it will fail to transmit data.

Workaround:

Connect a pullup resistor to Port B pin PB25 if it is configured to function as TXD3. The pin will then transmit normally.

### **CPM14. The ERAM4K Bit in the RISC Microcode Development Support Control Register (RMDS) is Erroneously Cleared.**

The ERAM4K bit is cleared in the RISC Microcode Development Support Control Register, RMDS, if the register's location is accessed as either part of a half-word or byte access.

Workaround:

If the ERAM4K is to be set, the RMDS must be accessed as part of a word starting at IMMR+9C4 to IMMR+9C7.

### **CPM15. USB underrun when ATM or Ethernet function is used in conjunction with USB.**

If both USB and ATM or Ethernet are used simultaneously, USB underruns will occur.

Workaround: Software should re-initialize the USB TX BD.

### **CPM16. USB endpoint lock up.**

When an endpoint is used only for receiving, there may be a case where this endpoint may lock up when an IN token is received to this endpoint. For example: 3 endpoints are set up on the 850 USB. Endpoint 0 being a control endpoint (usually both receive and transmit) and endpoint 1 is set up as a transmit-only endpoint and endpoint 2 set up as a receive-only endpoint. A lock up may occur on endpoint 1 when an IN token is received for endpoint 1. When this occurs, the 850 will fail to respond to this IN token. (Neither NACK nor ACK is given by the 850)

Workaround: Once the lock up is detected by the host software, the host can issue a “clear feature” command to reset the endpoint.

### **CPM 17. USB occasionally ignores tokens, violates USB protocol by providing incorrect responses, etc.**

A variety of erratic behavior occurs when a skew of greater than +8 or -20 ns is introduced between the differential USB rxd-p/rxd-n pair and the single USB RX data single. This condition causes the 850's USB module to misinterpret incoming tokens and data, further resulting in incorrect protocol responses.

Workaround: Add external logic to delay the differential input so that the skew will be less than +8 or -20 ns.

## **8.4 General Errata**

### **G1. Core Operation Is Limited to a 3.0V Minimum**

The current versions of the MPC850 silicon are only tested and verified at 3.0V–3.6V power. Because of this, low voltage operation at 2.2V cannot be used to power the core.

Workaround:

None.

### **G2. Higher Than Expected Keep Alive Power (KAPWR) Current When Main Power (VDDH & VDDL) Is Removed.**

There are four nodes within the MPC850 that are floating when VDDH and VDDL power is not supplied to the device. When this condition occurs, which is typical in Power Down Mode, the current drain on the Keep-Alive Power rail is greater than expected. (10 - 20 mA versus 10  $\mu$ A)

Workaround:

Provide adequate current source for KAPWR pin in Power Down Mode.

### **G3. EXTCLK and CLKOUT Clocks May Not Be in Phase in Half-speed Bus Mode.**

When the MPC850 uses EXTCLK as an input clock source and MF=001 in PLPRCR (i.e. the frequency of EXTCLK is 1/2 of the internal clock) and the half-speed bus mode is used (EBDF=01 in SCCR), the output clock from CLKOUT could be 90 degrees or 180 degrees out of phase from the input clock. This will affect synchronous designs where the same clock source is used as an input to EXTCLK, as well as to an external synchronous device (e.g. a peripheral or ASIC).

Workaround:

Case 1. Where multiple external devices need to operate synchronously with the MPC850:

Use the CLKOUT pin of the MPC850 as the source of clock for all external, synchronous devices (i.e. CLKOUT is the effective system master clock to be used for distribution).

Case 2. Where it is necessary to synchronize an external master clock (e.g. from a backbone), an MPC850, and external peripherals, to allow data transfers in all three directions:

There is no known workaround for this case. Use full-speed bus operation.

### **G4. Potential Problems Caused by Skew Between EXTCLK and CLKOUT.**

In correct operation, the PLL of the MPC850 will lock on the rising edge of the input clock. However, on these revisions of the MPC850, the PLL may lock on the falling edge of the input clock. This will affect the skew between EXTCLK and CLKOUT at the rising edge. The skew is dependent on the duty cycle of the input clock (but for a 50% duty cycle will not exceed 2nS). This will affect synchronous designs where the same clock source is used as an input to EXTCLK, as well as to an external synchronous device (e.g. a peripheral or ASIC).

Workaround:

Case 1. Where multiple external devices need to operate synchronously with the MPC850:

Use the CLKOUT pin of the MPC850 as the source of clock for all external, synchronous devices (i.e. CLKOUT is the effective system master clock to be used for distribution).


Case 2. Where it is necessary to synchronize an external master clock (e.g. from a backbone), an MPC850, and external peripherals, to allow data transfers in all three directions:

[NOTE: This workaround is a concept only. It has not been verified in hardware.]

Insert a PLL between the external master clock and the EXTCLK pin of the MPC850. Connect the phase comparison pin of the PLL to the CLKOUT pin of the MPC 860. Also use the CLKOUT signal as the reference clock for distribution to the local external peripherals.

Important Note: The PLL has to be capable of operating with a permanent offset of -2nS, therefore the range of lock should extend to about -4nS.

A diagram of this concept is given below:



## G5. ESD Breakdown Voltage for XFC Pin Less Than Motorola-Imposed Requirements.

The XFC pin (B2) of this version of the MPC850 silicon fails Motorola's XC qualification of 1 KV for the Electrostatic Discharge (ESD) breakdown voltage test. The maximum ESD voltage that can be applied to this pin on this silicon without damage is 750 volts.

Workaround:

Ensure that devices are not exposed to greater than 750 volts of electrostatic discharge.

## G6. Active Pullup Drivers Switch to High-Impedance Too Early.

The active pullup drivers (which include  $\overline{TS}$ ,  $\overline{TA}$ ,  $\overline{BI}$ , and  $\overline{BB}$ ) switch to high-impedance at a threshold voltage which is lower than the specified minimum output voltage level  $V_{OH}$ . Thereafter, the pullup resistor must pull the signal beyond the specified output voltage level. Depending upon the pullup resistor value and the capacitive load of the signal, this can result in a deassertion time which is longer than specified.

Workarounds:

Use a 1 k $\Omega$  pullup resistor for these drivers.

NOTE:

The long rise times do not cause a problem to the processor. Furthermore, in most systems, the longer rise times for these signals will also not present a problem for other devices.

1)  $\overline{TS}$  is normally sampled at the beginning of a bus cycle, and is thereafter a 'don't-care' until the cycle is terminated with  $\overline{TA}$ . Thus, a  $\overline{TS}$  which extends into the next clock cycles will be ignored.

2)  $\overline{BI}$  must only be in its negated state when sampled concurrently with  $\overline{TA}$  when a cycle is to a burstable target. In these systems, typically the only burstable target is the UPM, which will drive the  $\overline{BI}$  actively throughout cycles in which it is in control of the target. Therefore, this behavior will not affect operation of the memory controller. Furthermore, for burstable targets that are not in control of the memory controller, (A) the pullup resistor should have plenty of time to complete the signal deassertion before the  $\overline{TA}$  of the

cycle, and (B) the worst that could result from a falsely asserted  $\overline{BI}$  is that the master would break the burst into four accesses, resulting in a performance degradation but not a system failure.

3) For a non-burst cycle,  $\overline{TA}$  is normally sampled only once after  $\overline{TS}$  is driven.  $\overline{TA}$  is then a 'don't-care' until after the next  $\overline{TS}$  is driven. Therefore, there should be sufficient time for the pullup resistor to complete the signal deassertion of  $\overline{TA}$  before termination conditions for the next cycle are sampled. For burst cycles, typically the only burstable target in the system is the UPM, which drives the  $\overline{TA}$  signal actively until the completion of the entire burst cycle, thus avoiding the problem during the burst. And for other burstable targets, it is the responsibility of the target to meet the appropriate assertion/deassertion timing for  $\overline{TA}$ .

4) If this condition results in a long deassertion time for  $\overline{BB}$ , the only affect is increased latency between bus cycles as the bus is handed off between bus masters. That is, the bus would falsely appear busy for a short period after the on-chip master actually released the bus.

5)  $\overline{TS}$ ,  $\overline{TA}$ ,  $\overline{BI}$ , and  $\overline{BB}$  will typically be lightly loaded.

## G7. Restriction of open collector pull up.

Open collector signal may not be able to be pulled to greater than 3.5v

Workaround: Use external buffer if an open collector signal needs to be pulled to greater than 3.5V

## 8.5 CPU ERRATA

### CPU1. Bus Error Unsupported by the Data Cache Burst

The data cache does not support a bus error which might occur on the 2nd or 3rd data beat of a burst.

Also see CPU2.

Workaround:

Avoid using bus error in this case.

### CPU2. D-Cache Presents Valid Data When Parity Error Present on a Burst

If the LDST unit requests data that is not in the Data Cache, then the Data Cache will initiate a burst cycle to the memory. If during this burst cycle, a parity error is generated on the second or third words and not on the critical word; then the Data Cache will present the data to the LDST as the valid data.

Workaround:

Disable parity.

### CPU3. Incorrect Data Breakpoint Detection on Store Instructions

The data breakpoint mechanism comparison of operand data and operand size is faulty. If used, it can cause breakpoints where they should not occur, and conversely can miss breakpoints where they should occur.

Note: The instruction and address portions of the data breakpoint mechanism operate correctly. It is therefore still possible to use the data breakpoints to break on a store to a particular address and/or on a store instruction in a particular address range. Only the operand comparison portion of the data breakpoints does not function properly.

## CPU ERRATA

Workaround:

Do not use the operand comparison function of the data breakpoints for store instructions.

### CPU4. Program Trace Mechanism Error

In the following case there is an error in the program trace mechanism.

Program

0x00004ff0: divw. r25,r27,r26

0x00004ff4: divw. r28,r27,r26

0x00004ff8: unimplemented

0x00004ffc: b 0x00005010

where 0x00005010 belong to a page with a page fault.

The divide takes a long time to complete so the instruction queue gets filled with the unimplemented instruction, the branch and the branch target (page fault).

When the sequencer takes the unimplemented instruction it releases the fetch (that was blocked by the MMU error). This causes the queue to get another instruction in addition to the first page fault. Because the second fault is sequential to the branch target it is not reported by the queue flush (VF). This causes an incorrect value to be present in the VF flush information when the unimplemented exception occurs.

Workaround:

None.

### CPU5. Instruction Cache Replacement Policy Bug

I-cache replacement policy is not optimized. This does not affect the correctness of program execution, but will affect performance by an average of 10-20%. Once new silicon is available, performance should improve without any software changes required.

Workaround:

None.

### CPU6. Instruction MMU Bug at Page Boundaries in Show-all Mode

The wrong instruction address is driven by the core when all the following conditions occur:

1. MPC850 works in 'show all' mode (i.e. ISCT\_SER bits=000 in ICTRL)
2. Sequential instruction crosses IMMU page boundary
3. Instruction cache fails to get ownership of the internal U-bus on the first clock

In this case the address driven by the core will be of the previous page and not the current one.

The impact of this erratum has been deemed minimal, and it will therefore not be corrected.

Workaround:

Possible workarounds include:

1. Disable show all mode.



2. Invalidate the page next to current (by using the tlbie instruction) when performing the TLB reload operation.

## CPU7. Possible Data Cache Corruption When Writing SPRs

A write access to a special-purpose register located in caches, MMUs or SIU might corrupt the contents of the data-cache.

This may happen regardless of whether the cache is currently enabled or disabled (by either writing a disable command to the DC\_CST or by setting all regions to cache-inhibited in via MD\_CTR[CIDEF]). Thus, it is not possible to work around this problem by simply temporarily disabling the data cache.

NOTE: This is a probabilistic affect, caused by an internal race condition, and therefore does not occur in all cases. However, as it is due to a race condition, it is affected by all parameters which affect speed of the silicon (e.g. silicon revision, temperature, voltage). Therefore, if a system exhibits behavior which varies due to these factors, it is advisable to check for occurrence of this erratum.

The special-purpose registers affected by this include:

SPR	spr_address
=====	
IMMR	0x3d30
IC_CST	0x2110
IC_ADR	0x2310
IC_DAT	0x2510
DC_CST	0x3110
DC_ADR	0x3310
DC_DAT	0x3510
MI_CTR	0x2180
MI_AP	0x2580
MI_EPN	0x2780
MI_TWC	0x2b80
MI_RPN	0x2d80
MI_DBCAM	0x2190
MI_DBRAM0	0x2390
MI_DBRAM1	0x2590
MD_CTR	0x3180
M_CASID	0x3380
MD_AP	0x3580
MD_EPN	0x3780
M_TWB	0x3980
MD_TWC	0x3b80

## CPU ERRATA

MD_RPN	0x3d80
M_TW	0x3f80
MD_DBCAM	0x3190
MD_DBRAM0	0x3390
MD_DBRAM1	0x3590
DEC	0x2c00
TB Write	0x3880
TBU Write	0x3a80
DPDR	0x2d30

Workaround: There are two possible work-arounds:

1. If the contents of the TLBs are not changed dynamically (fixed-page structure), any access to the above-mentioned registers should be avoided (except for initialization).
2. If the contents of the TLBs are changed dynamically (pages are loaded on demand), then each "mtspr" instruction which accesses one of these registers must be preceded by a store word and a load word instruction of a data operand equal to the spr\_address of the respective register. As an example, to write the data from the general purpose register r1 to the special purpose register M\_TW, the following procedure should be followed:

```
lis r2, some_address_msb # an address in RAM
li r3, 0x3f80 # the spr_address of the M_TW from
                # the table
stw r3, some_address_lsb(r2) # no interrupts
lwz r3, some_address_lsb(r2) # between these
mtspr M_TW, r1 # 3 instructions
```

## CPU8. Branch Prediction with Sequential Branch Instructions

IF

there are three branches in sequence in the run-time program flow

AND

the third branch is in the mis-predicted path of the second branch,

THEN

although the third branch is part of a predicted path, it may be "issued" from the instruction queue. If this instruction issue in the mis-predicted path happens at the same time that the condition of the prediction is resolved (thereby causing mis-predicted instructions to be flushed from the instruction queue), then the resulting instruction cancellation will back up too far into the instruction queue. This will cause the instruction sequence starting from the instruction immediately preceding the first branch to be re-issued.

Notes:

1) Other factors of the internal state of the core also affect the occurrence of this behavior. Therefore, not all occurrences of this instruction sequences necessarily exhibit this behavior.

2) This behavior is not necessarily harmful to the user application. For example, the instruction preceding the first branch could be a simple move between registers.

3) Not all compilers generate this instruction sequence. The following compilers are known never to generate code that is susceptible to this erratum:

Diab Data (all versions)

Metaware

We are continuing to investigate other compilers with their vendors; their status is unknown at this time. We will update this list as our investigation progresses.

Workaround:

For every conditional branch preceded in program order by another branch:

1) IF

the two possible targets of the conditional branch consist of a branch instruction and a non-branch instruction

THEN

force the prediction of the conditional branch to predict the non-branch instruction (using the y-bit in the opcode of the conditional branch).

2) IF

both of the possible targets of the conditional branch are branch instructions

THEN

(1) insert a non-branch instruction before the branch on the predicted path

OR

(2) insert an 'isync' instruction before the first branch.

## CPU9. Missed Instruction After Conditional Branch

IF the instruction cache is enabled, THEN:

IF a conditional branch residing near the boundary of the current memory page is mis-predicted such that the CPU fetches beyond the page boundary

AND the branch target also resides on another memory page

THEN

the instruction at the branch target address may not be executed.

[The boundary of the current memory page is as follows:

1) If the MMU is enabled (MSR[IR]=1), then it is as defined by the associated MMU page table entry

## CPU ERRATA

2) If the MMU is disabled (MSR[IR]=0), then it is at a 4KB boundary.]

Note: This erratum depends also on the internal state of the core (instruction queue cancellation and MMU page swap), so it does not occur in all cases.

Workarounds:

- 1) Disable the instruction cache. This will cause the instruction to be fetched from external memory, and will therefore the instruction queue will not be filled until the branch is resolved.
- 2) Run the CPU in serialized mode (by programming the ICTRL[ISCT\_SER] bits). This mode will keep the predicted instructions from executing until the branch is resolved.
- 3) Avoid conditional branches with predicted paths that cross page boundaries.

### CPU10. Instruction Sequencer Error When Modifying MSR with Interrupts Enabled

IF the following instruction sequence occurs:

mtmsr Rx# change IR (Instruction Relocate) bit or PR (Problem  
# State) bit in MSR

op1

op2

AND external interrupts were previously enabled (or are being enabled by this mtmsr instruction)

AND an external interrupt or decrements interrupt occurs (or is already pending)

AND op1 not in the Instruction cache

AND the first instruction in the interrupt handler is fetched at the same clock that the op2 instruction is prefetched from external memory (as seen on the internal bus)

THEN the sequencer takes op2 as the first instruction in the interrupt handler. Also the sequencer and Instruction cache are out of sync in subsequent instruction fetched in the interrupt handler until a change of flow is executed. ("Change of flow" can also be isync and mtmsr commands.)

Workaround:

Do not execute mtmsr that changes IR or PR bits when external interrupt (and decrements interrupt) are enabled (i.e. when MSR[EE]=1). Allow at least two sequential instructions after the mtmsr that changes IR or PR before enabling interrupts.

### CPU11. Possible Excess Current Consumption in Deep Sleep Mode

Certain nodes of the multiplier hardware are not initialized at reset, and may thus result in non-destructive internal contention. As a result, if the processor is put into Deep Sleep mode without first putting the multiplier into a known state, current consumption in this mode may be higher than expected.

The impact of this erratum has been deemed minimal, and it will therefore not be corrected.

Workaround:

Execute a mullw instruction at any point after reset; this will put the internal nodes in an orderly state. Deep Sleep mode may then be entered at any time thereafter.

## 8.6 ATM ERRATA

### ATM1. APCO Interrupts Cannot Be Masked.

[Modes affected: All]

APCO interrupts cannot be masked with the IMASK field of the Receive Connection Table entry (RCT).

Workarounds:

Generally, if the APC is programmed well, there should not be any APCO. However, if they do occur and the user wants to mask them, they may use one of the following methods.

A. Implement a software workaround which will:

1. Ignore the specific APCO interrupts in the Interrupt table,

OR

2. Mask all interrupts globally by using GINT mask in IDMR1 or SCCM.

B. Download the RAM microcode package for enhanced UBR support. An enhancement supporting APCO masking has been integrated into this package.

### ATM2. CPM Lockup When Issuing APC\_BYPASS When TX Queue Full.

[Modes affected: All]

If a cell is scheduled for transmission via the APC\_BYPASS command when the transmit queue is full, the CPM will lock up, causing immediate failure of all channels.

In the case of a CPM lockup, the CPM must be reset. This can be accomplished either through the CPCR[RST] or by issuing an  $\overline{\text{SRESET}}$ .

This case should not happen during optimal operation. An overflow of the TX queue indicates that more transmit traffic has been scheduled than the physical layer can transmit, which is an error condition. Software should avoid this situation.

To fix this, the operation will be changed in the following fashion:

Operation will be changed such that this condition will not cause lockup, and an additional semaphore bit will be provided to assist in avoiding this situation.

Workaround: Monitor the transmit queue status, and do not issue the APC\_BYPASS command if the number of empty entries in the transmit queue is less than (NCITS+2).

### ATM3. Incorrect Operation in Presync State of Cell Delineation.

[Modes affected: Serial Receive]

If a HEC error occurs during the Presync state of the serial receive cell delineation state machine, incorrect operation occurs. Instead of moving back to the Hunt state, the receiver decrements Alpha by one, receives the cell into the Global Raw Cell Queue, and remains in the Presync state. The cell delineation state machine will move back to the Hunt state only when the Alpha parameter reaches zero. This erroneous operation can

## ATM ERRATA

result in long receive startup times, as decrementing Alpha can cause it to overflow back to 65535. The most common occurrence of this problem occurs when the lock is lost due to a line going down, and in the received cell sequence when restarting there are occurrences of both good and bad HECs.

Workaround:

IF at restart or in the case when lock state is lost

OR when the cell delineation state machine is not locked and the Global Raw Cell Queue contains more than 7 cells with HEC errors

THEN program Alpha = 1 and Delta = 6.

After programming these parameters, the user must check after at least 4 system clocks that these values were actually written to these parameters (and were not overwritten by the CPM).

[Note: A SYNC interrupt is issued in the case of loss of the lock state; see the description of the SYNC interrupt in the User's Manual.]

## Part 9 General Customer Information

Although not generally considered to be errata, the following items are guidelines for using the device appropriately.

### 9.1 CI-100. External Interrupt Handling

For external interrupt pins, if a request signal is a pulse, the interrupt request pin should be configured to “edge detect mode”. This ensures that the interrupt will be recognized even if interrupts are temporarily blocked or disabled by the software. The interrupt service routine (ISR) should clear the edge status flag after the ISR is entered and prior to setting the MSR’s EE bit (if it waits until after the EE bit is set, a second interrupt may be taken).

If a request signal is a “standard handshake”, the assertion is asynchronous, but the negation occurs upon request from the ISR. This ensures that the interrupt is taken and the source of the interrupt is known. The timing with respect to the EE bit is the same.

To avoid spurious interrupts, interrupt masks should not be set while interrupts might be sent to the core. Likewise, no interrupts should be disabled while the interrupt might be pending at the core. That way, when the core responds to the interrupt request, the request will still be pending and the core can determine the source of the interrupt. To accomplish all of the above, the EE bit should be disabled when masks are set or when interrupt enables are cleared.

### 9.2 CI-101. Move To Special Register (mtspr) Access to ICTRL Register

If you use mtspr to set the Ignore First Match (IFM) bit of the ICTRL register to 1 at the same time that you set an instruction breakpoint on this instruction, the chip will behave unpredictably.

Workaround:

Disable instruction breakpoints when setting the IFM bit.

### 9.3 CI-102. Concurrent Operation Of Ethernet & I2C or SPI Has Overlapping Parameter RAM Tables.

When concurrent operation of the Ethernet protocol and either I2C or SPI is set up and used at the same timer, there is an overlap in the parameter RAM.

Workaround: There is microcode available that moves the I2C/SPI parameter RAM entries to another location in the dual port RAM. To use this, download the description of the change and the object code file from the MPC8XX website. This package is called i2c\_spi.html, MPC8XX I2C/SPI Microcode Package.

## Part 10 General Documentation Errata Associated with Silicon Operation

The following items reflect additional information about the operation of the MPC850 and references made in the MPC850 User's Manual. Please refer to the manual for clarification.

### 10.1 DOC1. Cache-Inhibit Operation

In some cases, the last instruction executed from a certain page gets the caching inhibited attribute of the next page when the page change occurs between the time a fetch request was issued to the instruction cache and the time the instruction cache delivers the instruction to the sequencer. Since the instruction cache-inhibit is only used for performance reasons (mostly for not caching very fast memories or pages that include non real-time programs), the performance affect of this feature is negligible. See **Section 9 Instruction Cache** for more information.

### 10.2 DOC2. Updating the DAR and DSISR with Debug Counter Operation

If a load/store breakpoint occurs as a result of the debug counter expiring when a machine check interrupt occurs due to an error in a load/store cycle, a data storage interrupt, or an alignment interrupt occurs, set the DAR and DSISR registers to the affective address associated with the interrupting instruction. In some cases, when a load/store breakpoint occurs when one of the debug counters expires just before one of the above interrupts occurs, the value of the DAR and DSISR is changed. Although the interrupt is after the breakpoint and, therefore, should be ignored by the processor, the DAR and DSISR are updated. The value of the DAR and DSISR is normally used by the software inside these interrupt routines and may influence program flow only if these interrupts are nested one inside the other and a load/store breakpoint is used inside one of these interrupt routines. See **Section 6 Core** and **Section 20 Development Support** for details.

### 10.3 DOC3. XFC Capacitor Values Based on the PLPRCR [MF] Field.

Table 14-2 XFC Capacitor Values Based on PLPRCR[MF] in the MPC850 User's Manual (Rev. 0) on page 14-8 shows the recommended values for UDR (MPC850 rev.0) silicon.

The following table shows the recommended values for the XFC capacitor for CDR2 (MPC850 rev. A and later) silicon, along with the minimum and maximum values, as determined by the multiplication factor (MF).

XFC CAPACITOR VALUES				
MF RANGE	MINIMUM CAPACITANCE	RECOMMENDED CAPACITANCE	MAXIMUM CAPACITANCE	UNIT
MF ≤ 4	580*MF-100	680*MF-120	780*MF-140	pF
MF > 4	830*MF	1100*MF	1470*MF	pF





**DOC3. XFC Capacitor Values Based on the PLPRCR [MF] Field.**

**DOC3. XFC Capacitor Values Based on the PLPRCR [MF] Field.**

**HOW TO REACH US:****USA/EUROPE/LOCATIONS NOT LISTED:**

Motorola Literature Distribution  
P.O. Box 5405, Denver, Colorado 80217  
1-303-675-2140  
(800) 441-2447

**JAPAN:**

Motorola Japan Ltd.  
SPS, Technical Information Center  
3-20-1, Minami-Azabu Minato-ku  
Tokyo 106-8573 Japan  
81-3-3440-3569

**ASIA/PACIFIC:**

Motorola Semiconductors H.K. Ltd.  
Silicon Harbour Centre, 2 Dai King Street  
Tai Po Industrial Estate, Tai Po, N.T., Hong Kong  
852-26668334

**TECHNICAL INFORMATION CENTER:**

(800) 521-6274

**HOME PAGE:**

[www.motorola.com/semiconductors](http://www.motorola.com/semiconductors)

Information in this document is provided solely to enable system and software implementers to use Motorola products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits or integrated circuits based on the information in this document.

Motorola reserves the right to make changes without further notice to any products herein.

Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part.



Motorola and the Stylized M Logo are registered in the U.S. Patent and Trademark Office. digital dna is a trademark of Motorola, Inc. All other product or service names are the property of their respective owners. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

© Motorola, Inc. 2003

MPC850CE/D